65 993

## SECRET

24 SEP 68 15 372

S E C R E T 241457Z SEP 68 CITE 4640	25 <b>X</b> 1
PRIORITY	25X1
SUBJECT: EVALUATION OF GLASS LAMP MISSION G-043	*
1. QUALITY SUMMARY: IMAGERY OBTAINED ON THIS MISSION IS BETTER	
THAN RECENT GLASS LAMP MISSIONS. THE GROUND RESOLUTION AND INTER-	TSTRIBUTION
THE RELATION DUTINDICITE AND GOOD WHERE APPLICABLE CONDITIONS DO MADE	OFFICE P
DEGRADE THE IMAGERY. CLUUD COVER AND HAZE OBSCHRE APPROXIMATED WEST	Fine I
PERCENT OF THE ENTIRE MISSION.	CABLE SAC.
2. MISSION DATA:	PP&B/RD
A. THE STANDARD "B" CONFIGURATION CAMERA, UNIT NUMBER 10,	SHUCH.
WAS USED IN MISSION G-043 FLOWN 21 SEPTEMBER 1968. MODE 5 WAS USED THROUGHOUT.	TADL
B. FILM TYPE 3401 WAS USED THROUGHOUT THE MISSION	and following
	PSG/SC
PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.	RRD
C. CAMERA UNIT 10 HAS JUST COMPLETED OVERHAUL (IRAN)	REPRO
BY THE MANUFACTURER AND MISSION G-043 IS THE FIRST OPERATIONAL	AID
MISSION IN WHICH THE CAMERA HAS BEEN USED. THIS MISSION IS	TRE
THE FIRST OF RECENT GLASS LAMP MISSIONS TO USE FILM TYPE 3401.	PROD
3. ORIGINAL NEGATIVE:	SCIEN
	9
A. EXPOSURE: THE EXPOSURE IS ADEQUATE THROUGHOUT THE MISSION	EAST
and the control of th	M&S
and the control of th	PGM
	IAS
	DIA-XVA
PAGE 2 4640 S E C R E T	SPAD 25X1
B. DENSITY AND CONTRAST ARE GENERALLY MEDIUM.	DIA-AP
C. IMAGED DEGRADATIONS: (1) 9R SIDE: A MINUS DENSITY AREA IN THE SHAPE OF A	25X1
c (1) 9R SIDE: A MINUS DENSITY AREA IN THE SHAPE OF A SEMIRCLE 1.0 INCH IN DIAMETER IS IMAGED NEAR THE DATA	CMX
BLOCK THROUGHOUT THE MISSION. ROLLER CHATTER IS PRESENT	ļ
ON THE TITLED EDGE OF THE FIRST 200 FRAMES. A ROW OF MINUS	<u> </u>
ON THE TILLED EDGE OF THE FIRST ZWW FRANES. A ROW OF MINUS	ameration of
DENSITY DOTS 2.3 INCHES APART, 6.0 INCHES FROM THE TITLED EDGE IS PRESENT ON FRAMES 856 TO 866.	ADVANCE CY SAIRTERED
(2) 9L SIDE: NONE NOTED.	WITH TEXT
(3) BOTH SIDES: INTERMITTENT FAINT PLUS DENSITY STREAKS	
ARE PRESENT PARALLEL TO THE MAJOR AXIS OF THE FILM THROUGHOUT	Fig.
THE MISSION. THESE STREAKS DO NOT CONSTITUTE A SERIOUS IMAGE	***
DEGRADATION.	
D. PHYSICAL DEGRADATIONS:	
(1) 9R SIDE: HEAT SPLICES AND ASSOCIATED HANDLING	
MARKS ARE PRESENT BETWEEN FRAMES 910/911 AND IN FRAME	
594. A MANUFACTURING SPLICE IS PRESENT IN FRAME 848.	
(2) 9L SIDE: HEAT SPLICES WITH ASSOCIATED HANDLING	
MARKS ARE PRESENT BETWEEN FRAMES 910/911 AND IN FRAME 616.	
A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 934. A SMALL	:
EMULSION GOUGE IS PRESENT IN FRAME 616.	
	25X1
PAGE 3 4640 S E C R E T E. AUXILIARY DATA: THE FRAME COUNTER OPERATION WAS	20/(1
SLIGHTLY ERRATIC. THE COUNTER READ 0000 FOR THE FIRST FRAME,	
REPEATED NUMBER 532 FOR ONE EXTRA FRAME, AND REPEATED NUMBER	
CALED NUMBER JOS FOR ONE EATHA FRANCE, AND REFERIED NUMBER	

F. THE LAST TITLED FRAME ON BOTH SIDES IS 1123. THE PRINTING AND PROCESSING WERE GOOD.

4. THE PRINTING AND PROCESSING WERE GOOD.

SECRET

DIFFICULT TO READ.

END OF MSG



674 FOR NINE EXTRA FRAMES. THIS RESULTED IN A BIAS OF 11 BETWEEN THE TITLED FRAME AND FRAME COUNTER. THE CLOCK IS BLURRED AND

GROUP 1
Excluded from automatic downgrading and declassification